IMPROVED Township FAIRFIELD	MADISON	N CO. ROAD 53-C	RECORD	Sec
Class of Traffic			Shipp 	ing Point Distance
Built by		Date\ <b>8</b> 8	2	Price \$ 220200 p.mi.
Surveyed by C.Morse				• •
BRICK  Kind of foundation Thickness of foundation Make of brick Width Crown Cushion Filler Kind of curb Size of curb X    yds brick Cu. yds of base	CONCRETI Thickness Kind of Cement Mixture Material { Gravel Stone Width Crown Kind of expansion joints } Cu. yds. concrete	Bottor Top C Binde Width	I.AG—I.IMESTONE    Filter	Width 13' Crown 6" Cu. yds. Mat. 2543  50' wide from knownille West.
Total length 5.20 Distance C. to C. Ditch No. of stone culverts	No.	GENERAL cance berm to be of steel bridges		Width of R. W. 60 550 No. Con. bridges No. of wood bridges

No. of cor. pipe\_\_\_\_\_

No. of C. I. P.....

Depth of Ditches 25 min.

Total excavation...

Location on R. W. Center

## INSPECTION OF IMPROVED ROADS.

	1				- 1	i
Date of Inspection						
BRICK					Aor.	
Condition of brick			,	<u>-</u>	10	
Condition of filler		<del> </del>		ļ		
Condition of curb						10
CONCRETE			ŀ			
Condition of concrete				1		
Condition of surface						
SLAG-LIMESTONE						İ
Condition of foundation				<u> </u>		
Condition of top	<u> </u>					
Does top need to be scarified						
Are there ruts in road			<u> </u>			
GRAVEL						
Condition of surface	.		1	<u> </u>		· .
Is road ruted						
GENERAL						
Condition of ditches						
Condition of berms						
			1			-