IMPROVED Palestific - Kiousyill 1, 2000 THE COLUMBUS BLANK BOOK MEG. CO., COL., O. 5908 MADISON CO. ROAD RECORD							
Township PLEASAN	No54	<u> </u>	Sec				
Shipping Point							
Class of Traffic			Distance				
Built by	Date	87671881 &1882	Price \$ 135200 pmi.				
Surveyed by J. Arnett							
BRICK Kind of foundation Thickness of foundation Make of brick Width Crown Cushion Filler Kind of curb Size of curb X I yds brick Cu. yds of base	CONCRETE Thickness Kind of Cement Mixture Material { Gravel Slar Stone Width Crown Kind of expansion joints} Cu. yds. concrete	SLAG—LIMESTONE Filler	Crown 4 & 15 Cu. yds. Mat. 23443 - 2542				
Total length 4.6.8 Distance C. to C. Ditch No. of stone culverts No. of C. I. P. Depth of Ditches	miles. Distance ber No. of steel 1 No. concrete No. of cor.	m to berm 24' bridges culverts pipe been changed 11.9	Width of R. W. 45 & 50' No. Con. bridges No. of wood bridges Total excavation Location on R. W. Center.				

INSPECTION OF IMPROVED ROADS.

Date of Inspection						
BRICK						
Condition of brick					<u> </u>	
Condition of filler						
Condition of curb						
CONCRETE						
Condition of concrete						
Condition of surface						
SLAG—LIMESTONE						
Condition of foundation						
Condition of top						
Does top need to be scarified		·				
Are there ruts in road						
GRAVEL						
Condition of surface		1	1			
Is road ruted						
GENERAL				•		
Condition of ditches		1			<u> </u>	
Condition of berms			<u> </u>		<u> </u>	
Rel. Laid out 1831, Rerun 1875 See "Pal. Rd" " 1834 See K. & Col. Rd. Rd. Rd.	Rd. Rec. Nal, p306199	 1mproved 1882	Sec"Pal.Rd.Imp." "Warnersville"	Rd. Imp. Rec. Hol, , Rd. " " Hal.	page 392 page 43	
Rel. Laid out 1831. Rerun 1875 See "Pal. Rd. Rd. Rec. Nal, p308199 Improved 1882 See Pal. Rd. Imp. Rd. Imp. Rec. Nol, page 392 1834. See K. & Col. Rd. Rd. Rec. Nol, page 47 1881. Warnersville Rd Nal, page 43 Improved 1876. See Rob Rd. Imp. Com. J. Val. F. p. 341 R. 373						