IMPROVED					
Township FAIRFIELD	No. 102-	· C	Shipping Point		
		. Ship			
Class of TrafficH	ffic HEAVY		Distance		
Built by	Date	1868	Price \$ 15294.00		
Surveyed by J.W. Arnet	<b>t</b>		•		
BRICK	CONCRETE Thickness Kind of Cement Mixture  Material {Gravel	SLAG—LIMESTONE    Filler	Width 14. Crown 8. Cu. yds. Mat.		

No. of wood bridges.... Total excavation\_

No. Con. bridges.....

Width of R. W. 45

Location on R. W. Center

GENERAL Distance berm to berm\_\_\_\_28'

.miles. 36" + No. of steel bridges\_\_\_\_\_

No. concrete culverts.....

, 25

Total length 4.03

Distance C. to C. Ditch....

No. of stone culverts....

No. of C. I. P.....

Depth of Ditches.....

No. of cor. pipe\_\_\_\_\_

## INSPECTION OF IMPROVED ROADS.

Date of Inspection		-	•	÷ .	•
BRICK				}	
Condition of brick					
Condition of filler			<u> </u>	*	
Condition of curb					,
CONCRETE		. • • , •			
Condition of concrete					
Condition of surface	'				
SLAG—LIMESTONE			•		
Condition of foundation		-			
Condition of top					
Does top need to be scarified	<u> </u>		,	<u> </u>	<u> </u>
Are there ruts in road			1		<u> </u>
GRAVEL		, .			
Condition of surface			<u> </u>		<u> </u>
Is road ruted		•			
GENERAL	2હ	•	· .	- 17 AT	
Condition of ditches		•	<u> </u>		<u> </u>
Condition of berms			·		
Ref:-Laid-Outor verun 1841, See George	ville Rd. Rd.Rec.N	Lpage 72	<u> </u>	<u> </u>	<u>.                                    </u>
mproved 1868, See Comis J. Vol. C pag	e 362 & 425	<u> </u>		•	