

# Linson Road

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

**IMPROVED**

**MADISON CO. ROAD RECORD**

Township PAINT

No. 17-C

Sec. \_\_\_\_\_

Shipping Point \_\_\_\_\_

Class of Traffic HEAVY

Distance \_\_\_\_\_

Built by \_\_\_\_\_

Date 1870

Price \$ 10995.00

Surveyed by J. Arnett

BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler _____ Thickness { Center _____ Binder _____ Size _____ Thickness { Center _____ Filler _____ Size _____ Binder _____	Thickness <u>12"</u>
Thickness of foundation _____	Kind of Cement _____		Width <u>13'</u>
Make of brick _____	Mixture _____	Top Course { Thickness { Center _____ Filler _____ Size _____ Binder _____	Crown <u>8"</u>
Width _____	Material { Gravel _____ Slag _____ Stone _____	Binder, Method _____	Cu. yds. Mat. <u>2542 p.m.</u>
Crown _____	Width _____	Width _____	
Cushion _____	Crown _____	Crown _____	
Filler _____	Kind of expansion joints } _____	Cu. yds. Mat. _____	
Kind of curb _____			
Size of curb <u>X</u>	Cu. yds. concrete _____		
[ ] yds brick _____			
Cu. yds of base _____			

## GENERAL

Total length 4.76 miles.

Distance C. to C. Ditch \_\_\_\_\_

No. of stone culverts \_\_\_\_\_

No. of C. I. P. \_\_\_\_\_

Depth of Ditches 2½ (min)

Distance berm to berm 24'

No. of steel bridges \_\_\_\_\_

No. concrete culverts \_\_\_\_\_

No. of cor. pipe \_\_\_\_\_

Has location been changed No

Width of R. W. 45

No. Con. bridges \_\_\_\_\_

No. of wood bridges \_\_\_\_\_

Total excavation \_\_\_\_\_

Location on R. W. Center

# INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					