IMPROVED Township_Monroe	MADISON C	O. ROAD RECORD	Sec. Shipping Point		
Class of Traffic	HEAYY	· ,	Distance		
Built by	Date	9 1881-1874	Price \$ 1536 50		
Surveyed by J. Arnett			•		
BRICK Kind of foundation Thickness of foundation Make of brick Width Crown Cushion Filler Kind of curb Size of curb X yds brick Cu. yds of base	WidthCrown	Bottom { Filler	Thickness 12" Width 13' Crown 6" Cu. yds. Mat.		
Total length	No. of a	GENERAL, e berm to berm 28' steel bridges ncrete culverts cor. pipe eation been changed No	Width of R. W. 50' No. Con. bridges No. of wood bridges Total excavation Location on R. W. 4' E of &-		

INSPECTION OF IMPROVED ROADS.

Date of Inspection		<u> </u>			
BRICK					
Condition of brick					<u>'</u>
Condition of filler				-	<u> </u>
Condition of curb	, i				
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG-LIMESTONE				,	
Condition of foundation	· · ·	-			
Condition of top					
Does top need to be scarified	1		·		
Are there ruts in road					
GRAVEL					
Condition of surface			1		
Is road ruted					<u> </u>
GENERAL					
Condition of ditches		<u> </u>			<u> </u>
Condition of berms			<u> </u>		
Ref Laid out 1826, See Plummers Road	Rd. Rec. No. 1 page 2	 	<u> </u>		<u> </u>
mproved 1881 See Liverpool Road Rd. I 1874 Com.J	mp. Rec. No. I pagels	<u>56</u> !			
10 14	· *v: - Y~4 & OB	•			