

Rosedale-Plaincity Road
MADISON CO. ROAD RECORD.

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

IMPROVED

Township PIKE DARBY No. 24-C

Sec. _____

Shipping Point _____

Class of Traffic HEAVY

Distance _____

Built by _____ Date 1876

Price \$ 1600⁰⁰ p. mi.

Surveyed by J. Converse

BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler..... Thickness } Center..... Binder Size } Edge.....	Thickness <u>12"</u>
Thickness of foundation _____	Kind of Cement _____		Width <u>11'</u>
Make of brick _____	Mixture _____	Top Course { Thickness } Center..... Filler..... Size } Edge..... Binder	Crown <u>6"</u>
Width _____	Material { Gravel..... Slag..... Stone.....		Cu. yds. Mat. <u>1882⁷⁵</u> p. mi.
Crown _____	Width _____	Binder, Method _____	
Cushion _____	Crown _____	Width _____	
Filler _____	Kind of } expansion joints }	Crown _____	
Kind of curb _____		Cu. yds. concrete _____	Cu. yds. Mat. _____
Size of curb <u>X</u>			
<input type="checkbox"/> yds brick			
Cu. yds of base _____			

GENERAL

Total length 4.80' miles.
 Distance C. to C. Ditch _____
 No. of stone culverts _____
 No. of C. I. P. _____
 Depth of Ditches 2' (min)

Distance berm to berm 26'
 No. of steel bridges _____
 No. concrete culverts _____
 No. of cor. pipe _____
 Has location been changed No

Width of R. W. 45'
 No. Con. bridges _____
 No. of wood bridges _____
 Total excavation _____
 Location on R. W. Center

INSPECTION OF IMPROVED ROADS.

Date of inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					

Ref. - Laid out 1855. See "Converse Road" R. Rec. No. 1, page 38. Improved. - 1876. See "Chuckery & Plain City Pike" Com's. J. Vol. E page 330 + 366, "Weaver & Plain City Pike" Com's. J. Vol. E. page 279 & 378
 Altered 1860. See "Hunt's Alt." R. Rec. No. 1, page 129
 1865. See "Boyd & Bowers Alt." R. Rec. No. 1, page 156

**Rosedale - Plain City Road
MADISON CO. ROAD RECORD**

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

IMPROVED

Township PIKE

No. 24-T

Sec. _____

Shipping Point _____

Class of Traffic MEDIUM

Distance _____

Built by _____

Date _____

Price \$ _____

Surveyed by _____

BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler _____ Thickness } Center _____ Binder _____ Size _____ Edge _____	Thickness _____
Thickness of foundation _____	Kind of Cement _____		Width _____
Make of brick _____	Mixture _____	Top Course { Thickness } Center _____ Filler _____ Size _____ Binder _____	Crown _____
Width _____	Material { Gravel _____ Slak _____ Stone _____		Cu. yds. Mat. _____
Crown _____	Width _____	Binder, Method _____	
Cushion _____	Crown _____	Width _____	
Filler _____	Kind of expansion joints } _____	Crown _____	
Kind of curb _____		Cu. yds. concrete _____	Cu. yds. Mat. _____
Size of curb _____ X			
<input type="checkbox"/> yds brick _____			
Cu. yds of base _____			

GENERAL

Total length 3.00 miles.

Distance C. to C. Ditch _____

No. of stone culverts _____

No. of C. I. P. _____

Depth of Ditches _____

Distance berm to berm _____

No. of steel bridges _____

No. concrete culverts _____

No. of cor. pipe _____

Has location been changed _____

Width of R. W. _____

No. Con. bridges _____

No. of wood bridges _____

Total excavation _____

Location on R. W. _____

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					

Ref. Laid out 1833. See "Converse Rd." Rd. Rec. No. 1, page 38
 Altered 1860. See "Hunt's Alt. Rd. Rec. No. 1, p 129
 .. 1865. See "Boyd & Bowers Alt. Rd. Rec. No. 1, page 156