IMPROVED Township PINE	Meaver Road MADISON CO. ROAD RECORD No. 28-C NOW 25-C			Shipping Point		
Class of Traffic	HEAVY			Distance		
Built by		Date	1890-90	Price \$		
Surveyed by J. Afnett						
BRICK Kind of foundation Thickness of foundation Make of brick Width Crown Cushion Filler Kind of curb Size of curb X yds brick Cu. yds of base	CONCRE Thickness Kind of Cement Mixture Material {Gravel Slone Width Crown Kind of expansion joints } Cu. yds. concrete		SLAG—LIMESTONE Bottom Filler Thickness Center Binder Size Thickness Center Filler Filler Size Binder. Method Width Crown Cu. yds. Mat	Width //O' Crown 6 6" Cu. yds. Mat. 1956 p.m.		
Total length 2.90 Distance C. to C. Ditch No. of stone culverts No. of C. I. P. Depth of Ditches	No	o. of steel brook. concrete of cor. pi	to berm	Width of R. W. 50' No. Con. bridges No. of wood bridges Total excavation Location on R. W. 4' 10 5 (4)		

INSPECTION OF IMPROVED ROADS.

Date of Inspection		<u> </u>	_		
BRICK					
Condition of brick					
Condition of filler					<u> </u>
Condition of curb					ļ
CONCRETE			-		
Condition of concrete		,			ļ
Condition of surface					
SLAG—LIMESTONE					·
Condition of foundation					-
Condition of top					
Does top need to be scarified					
Are there ruts in road					1
GRAVEL					
Condition of surface			·		
Is road ruted		<u> </u>	<u> </u>	1	
GENERAL				·	
Condition of ditches		1	· ·	<u> </u>	: :
Condition of berms		<u> </u>	<u> </u>		1
Ref. Laid out mproved 1890. See Weaver Rd. Maz. Ad	.Imp. Rec. No. 2 p. 198		l .		
mproved 1890. See Weaver Rd. Maz: Rd	. Imp. Rec. No. 2 p. 198	-			