

IMPROVED

Selsor-Moon Road

MADISON CO. ROAD RECORD

Township STOKES RANGE _____ No. 16-C

Sec. _____

Shipping Point _____

Class of Traffic HEAVY

Distance _____

Built by _____ Date 1903 Price \$ 17600⁰⁰Surveyed by J. H. Asher

BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler _____	Thickness <u>12"</u>
Thickness of foundation _____	Kind of Cement _____	{ Thickness { Center _____	Width <u>12"</u>
Make of brick _____	Mixture _____	{ Binder _____	Crown <u>8"</u>
Width _____	Material { Gravel _____	{ Size _____	Cu. yds. Mat. _____
Crown _____	{ Slag _____	Top Course { Thickness { Center _____	
Cushion _____	{ Stone _____	{ Filler _____	
Filler _____	Width _____	{ Size _____	
Kind of curb _____	Crown _____	{ Binder _____	
Size of curb <u>X</u> _____	- Kind of } _____	Binder, Method _____	
☐ yds brick _____	expansion joints } _____	Width _____	
Cu. yds. of base _____	Cu. yds. concrete _____	Crown _____	
		Cu. yds. Mat. _____	

GENERAL

Total length 6.85 miles.Distance berm to berm 24'Width of R. W. 45' 8' 40"

Distance C. to C. Ditch _____

No. of steel bridges _____

No. Con. bridges _____

No. of stone culverts _____

No. concrete culverts _____

No. of wood bridges _____

No. of C. I. P. _____

No. of cor. pipe _____

Total excavation _____

Depth of Ditches 1 1/2' (min)Has location been changed NoLocation on R. W. Center

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					

[illegible]