IMPROVED Township DEERCREEY	MADISON CO. R	ROAD RECORD	Sec
Class of Traffic MES	DIUM		ping Point Distance
Built by	Date	***************************************	Price \$
Surveyed by			
BRICK  Kind of foundation Thickness of foundation Make of brick Width Crown Cushion Filler Kind of curb Size of curb L   yds brick Cu. yds of base	CONCRETE Thickness Kind of Cement Mixture  Material {Gravel Sing Stone Width Crown Kind of expansion joints} Cu. yds. concrete	SLAG—LIMESTONE  Filler	Thickness Width Crown Cu, yds, Mat.
Total length 2.67 Distance C. to C. Ditch No. of stone culverts No. of C. I. P. Depth of Ditches	No. of steel br	to berm	Width of R. W No. Con. bridges No. of wood bridges Total excavation Location on R. W

## INSPECTION OF IMPROVED ROADS.

Date of Inspection		• • • •		• •	
BRICK					
Condition of brick					
Condition of filler					
Condition of curb		,			
CONCRETE					
Condition of concrete			<del></del>		
Condition of surface					
SLAG—LIMESTONE		·			
Condition of foundation					
Condition of top	•		ļ	70-	,
-Does top need to be scarified				7	1
Are there ruts in road			<u> </u>	<u> </u>	<u> </u>
GRAVEL		•			
Condition of surface		1		<u> </u>	<u> </u>
Is road ruted		ļ		1	1
GENERAL				Sim " water	
Condition of ditches	•		·	<del> </del>	<u> </u>
Condition of berms		<u> </u>	<u> </u>		1
Laid out 1841. Simson Road" Rd. Hec. No. 1	. Page 70	<u> </u>	<u> </u>	<u>L</u>	<u> </u>
Altered 1842 "Adain All." Ad. Rec. Mo.	1 75				