

West Jefferson-Kiousville Road MADISON CO. ROAD RECORD

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

IMPROVED

Township JEFFERSON, FAIRFIELD

No. 22 - C

Sec. A
West. J. To Jc. No 102

Shipping Point _____

Class of Traffic HEAVY

Distance _____

Built by _____

Date 1869

Price \$ 2562⁰⁰ p.m.

Surveyed by J. Arnett

BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Thickness { Center _____ Edge _____ Binder _____ Size _____	Thickness <u>12"</u>
Thickness of foundation _____	Kind of Cement _____		Width <u>13'</u>
Make of brick _____	Mixture _____		Crown <u>8"</u>
Width _____	Material { Gravel _____ Slag _____ Stone _____	Top Course { Thickness { Center _____ Edge _____ Filler _____ Size _____ Binder _____	Cu. yds. Mat. _____
Crown _____			
Cushion _____			
Filler _____	Width _____	Binder, Method _____	
Kind of curb _____	Crown _____	Width _____	
Size of curb <u>X</u>	Kind of expansion joints { _____	Crown _____	
<input type="checkbox"/> yds brick		Cu. yds. Mat. _____	
Cu. yds of base _____	Cu. yds. concrete _____		

GENERAL

Total length 3.70 miles.

Distance C. to C. Ditch _____

No. of stone culverts _____

No. of C. I. P. _____

Depth of Ditches 3' min.

Distance berm to berm 26'

No. of steel bridges _____

No. concrete culverts _____

No. of cor. pipe _____

Has location been changed No

Width of R. W. 45

No. Con. bridges 1

No. of wood bridges _____

Total excavation _____

Location on R. W. Center

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					

West Jefferson - Kioussville Road

MADISON CO. ROAD RECORD

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

IMPROVED

Township FAIRFIELD No. 22 - C

Sec. B
Jc. No. 102 TO Jc. No. 53

Shipping Point _____

Class of Traffic _____ Distance _____

Built by _____ Date 1878 Price \$ 1.564²⁹ p. mi.

Surveyed by J. Arnett

BRICK	CONCRETE	SLAG—LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler _____	Thickness <u>12"</u>
Thickness of foundation _____	Kind of Cement _____	{ Thickness } Center _____	Width <u>13'</u>
Make of brick _____	Mixture _____	{ Binder _____	Crown <u>6"</u>
Width _____	Material { Gravel _____	{ Size _____	Cu. yds. Mat. <u>2542</u> p. mi.
Crown _____	{ Slag _____	Top Course { Thickness } Center _____	
Cushion _____	{ Stone _____	{ Filler _____	
Filler _____	Width _____	{ Size _____	
Kind of curb _____	Crown _____	{ Binder _____	
Size of curb _____ <u>X</u>	Kind of expansion joints } _____	Binder, Method _____	
[] yds brick _____	Cu. yds. concrete _____	Width _____	
Cu. yds of base _____		Crown _____	
		Cu. yds. Mat. _____	

GENERAL

Total length 6.34 miles.
Distance C. to C. Ditch _____
No. of stone culverts _____
No. of C. I. P. _____
Depth of Ditches 2 1/2 min.

Distance berm to berm 24'
No. of steel bridges _____
No. concrete culverts _____
No. of cor. pipe _____
Has location been changed No

Width of R. W. 50'
No. Con. bridges _____
No. of wood bridges _____
Total excavation _____
Location on R. W. Center

INSPECTION OF IMPROVED ROADS.

Date of Inspection_____					
BRICK					
Condition of brick_____					
Condition of filler_____					
Condition of curb_____					
CONCRETE					
Condition of concrete_____					
Condition of surface_____					
SLAG—LIMESTONE					
Condition of foundation_____					
Condition of top_____					
Does top need to be scarified_____					
Are there ruts in road_____					
GRAVEL					
Condition of surface_____					
Is road rutted_____					
GENERAL					
Condition of ditches_____					
Condition of berms_____					