IMPROVED MADISON CO. ROAD RECORD									
Township FAIRFIELD J	efferson	No103	<u>- C</u>	Sec					
•	Shipping Point								
Class of Traffic H	EAVY	**************************************	·						
Built by	***************************************	Date_186	8.80897	Price \$ 3653					
Surveyed by J.W.Arnett - H. L. McCatferty									
BRICK	CONC	RETE	SLAG-LIMESTONE	GRAVEL					
	Thickness Kind of Cement. Mixture Material { Gravel	5}	Bottom Filler Center Center Edge Edge Center Cente	Thickness 12" Width 1110' Crown 6" Cu. yds. Mat.					
Total length 3.70 Distance C. to C. Ditch No. of stone culverts No. of C. I. P. Depth of Ditches		No. of steel br No. concrete No. of cor. pi	culvertseen changed_~No	Width of R. W. 50' No. Con. bridges No. of wood bridges Total excavation Location on R. W. Center					

INSPECTION OF IMPROVED ROADS.

Date of Inspection	¢	O!		10 2 4 52 5	<u>.</u>
BRICK.					
Condition of brick			1	<u>.</u>	
Condition of filler	• •				
Condition of curb					
CONCRETE		٠.			•
Condition of concrete		•			 -
Condition of surface				<u> </u>	
SLAG—LIMESTONE .	•			_	
Condition of foundation	<u></u>	•			
Condition of top		·		·	<u> </u>
Does top need to be scarified					
Are there ruts in road					<u></u>
GRAVEL			•		
Condition of surface	-		<u> </u>	<u> </u>	<u> </u>
Is road ruted					
GENERAL				- ميوه	
Condition of ditches				· · · · · · ·	1
Condition of berms					<u> </u>
RefLaid out-1834. See "Willson Road" Rd.	Rec. No.Lpage 35	<u> </u>	<u> </u>		<u> </u>
mproved 1868 See L. & G. Rd. Imp. Com. J. Vol. C.	Page 362 8 42	ာ <u> </u>			