

3/4" IRON PIPES FOUND (DAMAGED) 12.42' BETWEEN PIPES


ELMHURST VILLAGE NO. 1 PLAT BK. 1, PG. 362 LOT NO. 11

WILLIAM H. GRUBBS DEED BK. 155, PG. 365 0.301 AC., TAX MAP NO. 379

RODNEY A. AND ROSEMARY A. BELL 1.385 AC., DEED BK. 179, PG. 177 PARCEL NO. 64

EDMUND A. AND MARY B. DWYER

ERCELL L. CONVERSE DEED BK. 193, PG. 149 0.95 AC., TAX MAP NO. 180 AND 181



CITY OF LONDON, MADISON COUNTY, OHIO

V.M.S. 6324

BEING PART OF A 0.258 ACRE TRACT RECORDED IN DEED BOOK 155, PG. 391 AND PART OF A 1.020 AC. TRACT RECORDED IN DEED BK. 151, PG. 281.

TOTAL OF 0.0889 ACRES, BEING 0.0100 AC. OUT OF THE 0.258 AC. AND 0.0789 AC. OUT OF THE 1.020 AC.

DRAWN BY: NB	CHECKED BY: 11
I HEREBY CERTIFY THAT THE HEREON PLATTED PROPERTY WAS MEASURED TO ACCEPTABLE SURVEY STANDARDS	
<i>Neil Babb</i>	13 OCT 1984
NEIL BABB P.S. 5969	DATE
JOB NO 6184	34-84

BABB ENGINEERING & SURVEYING
 209 LAFAYETTE ST., P.O. BOX 374
 LONDON, OHIO 43140
 TELE 614-852-4121