

GRANTOR: Dimar Associates D.B. 277, Pgs. 821-823

PREPARED


LOCATION: Village of Jefferson
VMS 6202 & 12148

- ⊗ Indicates RR Spike Found
- Indicates iron pin Found
- Indicates 3/4" iron pipe set

ACREAGE: 3.7540, 4.1586 and 1.7121 Ac. out
of original 9.624 ac.



NATIONAL ROAD (US 40)



Columbian Homes, Inc.
13,1939 Ac.
D.B. 277, Pg. 99

3.7540 Ac.

4.1586 Ac.

1.7121 Ac.

Village of Jefferson
1.746 Ac.
D.B. 269, Pg. 363


D. & R. Long
D.B. 221, Pg. 313
1.107 Ac.

L. & S. Rice
D.B. 239, Pg. 52
1.266 Ac.

INWOOD ROAD

LINE	BEARING	DISTANCE
L 1	S 02°52'45" E	51.58

West-Wood Estates, Sec. 4, Pt. 3 and Sec. 3



I hereby certify that the hereon
plotted property was surveyed to
acceptable standards and that the
error of closure does not exceed 0.02'.

Roger E. Thompson
Roger E. Thompson, PS 6552



THOMPSON SURVEYING
2005 DEER RUN LANE
LONDON, OHIO 43140

May, 1989

45-89