GRANTOR: HUNTINGTON NATIONAL BANK, HENRY H. BLAU, JR., CAROLYN B PEROT. & ELIZABETH B. STICKNEY, TRUSTEES LOCATION: MADISON COUNTY, CANAAN TWP., VMS 6589, 7082 & 7832 ACREAGE: 124.6912 AC. BEING ALL OF AN 80.0 ACRE TRACT, ALL OF AN 11.806 ACRE TRACT AND PART OF A 143.64 ACRE TRACT AS RECORDED IN D.B. 263, PGS. 305-309 ALLEN & MARY L. YUTZY 171/276 POWELL DITCH # 2 NO FENCE ALONG DITCH S 87 38 '00 'E (REF. BRG. 651.64' MOLER FAMILY FARMS 258/9 P.O.B. VMS 9530 VMS 7082 124.6912 ACRES NO FENCE THIS LINE N. 89 25.50.M Note: The bearings shown on this survey are based on the bearings shown on an 11. 806 Ac. tract as recorded MARTIN L. & MARTHA E. STAHL FOR BUILDING
LOCATION SEE
TOP RIGHT
CORNER OF THIS in Vol. 263, Pgs 305-309 of the Madison County 263/279 LEGAL DESCRIPTION EASEMENTS 124.6912 ACRES Deed Records in the County Recorder's Office. DEED BOOK 123. PG. 810 COLUMBUS SOUTHERN OHIO ELECTRIC Situated in the State of Ohio, County of Madison, Township of Canaan, VMS 6589, 7082 & 7832, being all of an 80.00 acre tract, all of an 11.806 acre tract and part of an original 143.64 acre . | DRAWING tract all in the name of The Huntington National Bank, Henry H. Blau, Jr., Carolyn B. Perot, and Elizabeth B. Stickney, Trustees (hereafter refered to as HNB) as recorded in deed book 263, pgs. 305-309 and being more particularly described as follows: * 2. DEED BOOK 148. PG. 202 COLUMBUS SOUTHERN OHIO ELECTRIC SURVEYOR'S CERTIFICATE
124.6912 Acre Survey The undersigned hereby certifies to Thomas R. & Robin W. Green and to Chicago Title Insurance Company, as of January 17, 1992, as follows: this survey was actually made upon the ground; NOTE: FENCE OCCUPIES P/L EXCEPT WHERE NOTED Beginning at an iron pin found in the center of Plain City-Georgesville Road, said point being the northeast corner of HNB's 64.72 acre tract and the southeast corner of of a tract in the name of Norman E. Dolder, etal., deed book 268, pg. 510, thence with the center of said road, S 36 deg. 07' 02" W, 816.91 feet to an iron pin found at an angle point in said road; it and the information, courses and distances shown on the plat of survey are correct; the title lines and lines of actual possession are the same; the property description "closes" by engineering calculation; this survey correctly shows the size, location and type of all buildings, structures and other visible improvements on the property and all are within the boundary Thence continuing the center of said road, S 18 deg. 36' 22" W, 883.68 feet to an iron pin found at the northeast corner of a 0.59 acre tract in the name of Jack L. & Karen F. Cordle; lines and applicable set-back lines, unless otherwise shown hereon, (whether established by a subdivision plat, recorded LEGEND Thence with the following two lines between HNB and Cordle, (1) N 76 deg. 50' 06" W, 259.30 feet to an iron pin; (2) S 18 deg. 36' 22" W, 100.00 feet to an iron pin and in the north line of a tract restrictions or applicable zoning or building codes) affecting the property; there are no easements, encroachments or uses O IRON PIN FOUND affecting the property appearing from a careful physical inspection of the same, other than those shown on the plat of survey; all utility services necessary for the normal operation in the name of Martin L. & Martha E. Stahl, deed book 263, pg. 279; STONE FOUND of the property are present on the property or within an adjacent Thence with the following three lines between HNB and Stahl, (1) N 76 deg. 50' 06" W, 310.70 feet to a wood corner post; (2) N 3 deg. 09' 48" W, 1034.72 to a found stone; and (3) N 89 deg. 52' 20" W, 3944 79 feet to a found stone in the east line of a tract in the name of Moler Family Farms, Ltd., deed book 258, pg. 9; public right-of-way or recorded easement; there are no encroachments on adjoining premises, streets or alleys by any of WOOD CORNER POST FOUND BEARING DISTANCE said buildings, structures or other visible improvements or S 18 36 22 N 84 20 49 S 72 27 28 S 67 17 00 S 40 21 07 S 73 29 34 N 73 48 26 N 73 48 26 N 100.00 223.84 172.35 195.89 176.21 239.47 216.80 162.21 encroachments onto the subject property by any visible improvements situated upon any adjoining premises. Thence with the line between HNB and Moler Family Farms, Ltd., N 3 deg. 02' 28" E, 907.90 feet to a found iron pin on the top of the south ditch bank of the Powell Ditch # 2, said point being the northeast corner of HNB's 11.806 acre tract and on the south line This survey was made in accordance with the "Minimum Standard Detail Requirements for Land Title Surveys" jointly established by ALTA and ASCM in 1988 and meets the accuracy requirements of a Class B survey, as defined therein. of a tract in the name of Allen & Mary L. Yutzy, deed book 171,pg. Thence following the meanderings of the top of the south ditch bank the following thirteen (13) courses, (1) S 87 deg. 38' 00" E, 651.64 feet to a found iron pin; (2) N 78 deg. 10' 21" E, 708.20 feet to a found iron pin; (3) S 76 deg. 18' 55" E, 498.46 feet to a found iron pin; (4) N 84 deg. 20' 49" E, 223.84 feet to a found iron pin; (5) S 72 deg. 27' 28" E; 172.35 feet to a found iron pin; (6) N 87 deg. 14' 32" E, 287.78 feet to a found iron pin; (7) N 46 deg. 06' 32" E, 417.92 feet to a found iron pin; (8) N 74 deg. 45' 51" E, 362.99 feet to a found iron pin; (9) S 67 deg. 17' 00" E, 195.90 feet to a found iron pin; (10) S 40 deg. 21' 07" E, 176.21 feet to a found iron pin; (11) S 73 deg. 29' 34" E, 239.47 feet to a found iron pin; (12) N 73 deg. 48' 26" E, 216.80 feet to a found iron pin; and (13) N 56 deg. 51' 30" E, 162.21 feet to a found iron pin at the northeast corner of HNB's 11.806 acre tract and in the east line of a tract in the name of Norman E. Dolder, etal., deed book 268, pg. 510; 1. In my opinion, the easement to the State of Ohio, of The hereon platted property does not occupy any flood hazard area of record. record in Deed Book 128, Pg. 124, Recorder's Office, Madison County, Ohio does not apply to the subject property. 2. In my opinion, the easement to Columbus and Southern Ohio Electric Company, of record in Deed Book 142, Pg. 269, Recorder's Office, Madison County, Ohio does not apply to the JACK L. & KAREN F CORDLE 230/144 3. In my opinion, the subject property has access to the Powell Ditch #2 located along the northern boundary of the THOMPSON 4. The Powell Ditch #2 was improved in accordance with Sec. 6131 O.R.C. and is subject to the maintenance provisions of Sec. 6137 O.R.C. The Madison County Engineer should be contacted for further information concerning this ditch. Thence with the following three lines between HNB and Dolder, (1) S 10 deg. 47' 29" W, 242.70 feet to a wood corner post; (2) S 20 deg. 02' 30" E, 466.03 feet to a wood corner post; and (3) S 87 deg. 31' 12" E, 1168.02 feet to the point of beginning. The herein described tract contains 124.6912 acres. Prepared from a field survey done in November 1991 R.E. THOMPSON SCALE IN FEET ENGINEERING & SURVEYING CO survey done in November, 1991. 2005 DEER RUN LANE Roger E. Thompson, PS 6552 LONDON. OHIO 43140 NOVEMBER. 1991

REVISED JANUARY. 1992

28-92