**Title \*** Lafayette Plain-City DAR-5-13.71

**Culvert/Bridge Number** 

**Geo Location** 40.101351245494826 -83.29346761107446

**General Appraisal** 9 As built condition

Span Size 30inchCulvert Length 40ftSize of Culvert 30 inch

## Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

Material 9 EXCELLENT

**Conduit Alignment** 9 EXCELLENT

**RCP** 

**Shape** 9 EXCELLENT

**Seams and Joints** 9 EXCELLENT

Slab

**Abutments** 

Type Culvert

**Headwalls** 

**End Structure** 

## Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.

**Conduit Waterway Blockage** 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.

Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

## Approaches

**Pavement** 9 Excellent No noticeable defects.

Guardrail

**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.

**Comments** Additional culvert 68x30 rated 9

Owner Rapp, Aaron

**Completed DateTime** 12/02/2024 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage