

Title * Lafayette-Plain City MON-5-4.65
Culvert/Bridge Number MON-5-4.65
Geo Location 40.00413272245593 -83.39099541306496
General Appraisal 9 As built condition
Span Size 68 inch
Culvert Length 40ft
Size of Culvert 43x68
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Brush needs cut at inlet
Owner Rapp, Aaron
Completed DateTime 11/26/2024 12:00:00 AM
Request Category Crack Seal
Group Ops-Drainage