

IMPROVED

MADISON CO. ROAD RECORD

Township DARBYNo. 40-C

Sec. _____

Shipping Point _____

Class of Traffic HEAVY

Distance _____

Built by _____

Date 1894Price \$1078¹⁰ p.m.Surveyed by H. L. McCafferty

BRICK

CONCRETE

SLAG-LIMESTONE

GRAVEL

Kind of foundation _____
 Thickness of foundation _____
 Make of brick _____
 Width _____
 Crown _____
 Cushion _____
 Filler _____
 Kind of curb _____
 Size of curb X
☐ yds brick
 Cu. yds of base _____

Thickness _____
 Kind of Cement _____
 Mixture _____
 Material ☐ Gravel
 ☐ Slag
 ☐ Stone
 Width _____
 Crown _____
 Kind of expansion joints ☐
 Cu. yds. concrete _____

Bottom ☐ Filler
 ☐ Thickness ☐ Center
 ☐ Binder ☐ Edge
 ☐ Size
 Top Course ☐ Thickness ☐ Center
 ☐ Filler ☐ Edge
 ☐ Size
 ☐ Binder
 Binder, Method _____
 Width _____
 Crown _____
 Cu. yds. Mat. _____

Thickness 12"
 Width 12'
 Crown 6"
 Cu. yds. Mat. _____

Length Const
Incorporated1.15 mi
045'

GENERAL

Total length 0.70 miles.
 Distance C. to C. Ditch 30
 No. of stone culverts 1
 No. of C. I. P. 2
 Depth of Ditches 2' min
 No Vit. P. 2

Distance berm to berm 26'
 No. of steel bridges _____
 No. concrete culverts _____
 No. of cor. pipe _____
 Has location been changed No

Width of R. W. 50'
 No. Con. bridges _____
 No. of wood bridges _____
 Total excavation _____
 Location on R. W. N. Side