

IMPROVED

Township Stokes

Shady Grove Road

MADISON CO. ROAD RECORD

No. 153-C

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

Sec. _____

Shipping Point _____

Class of Traffic _____

Distance _____

Built by _____

Date _____

Price \$ _____

Surveyed by _____

BRICK	CONCRETE	SLAG—LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler _____ Thickness } Center _____ Binder _____ Size _____	Thickness _____
Thickness of foundation _____	Kind of Cement _____		Width _____
Make of brick _____	Mixture _____		Crown _____
Width _____	Material { Gravel _____ Sand _____ Stone _____	Top Course { Thickness } Center _____ Filler _____ Size _____ Binder _____	Cu. yds. Mat. _____
Crown _____			Binder, Method _____
Cushion _____			Width _____
Filler _____	Crown _____	Crown _____	
Kind of curb _____	Kind of expansion joints } Cu. yds. concrete _____	Cu. yds. Mat. _____	
Size of curb _____ X _____			
_____ yds brick _____			
Cu. yds of base _____			

GENERAL

Total length 0.04 miles.

Distance C. to C. Ditch _____

No. of stone culverts _____

No. of C. I. P. _____

Depth of Ditches _____

Distance berm to berm 3-16-3

No. of steel bridges _____

No. concrete culverts _____

No. of cor. pipe _____

Has location been changed _____

Width of R. W. 40'

No. Con. bridges _____

No. of wood bridges _____

Total excavation _____

Location on R. W. _____

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					