SOUTH FACE CONC. BLOCK. BLDG. EXTENDED EAST SET IN GRAPE ARBOR N.88°47'53"E. 172.55' ROGER BENNETT et.al. 102.97 AC. D.B. 270 , PG. 22 1.2914 AC. NO FENCE PASS AT 244.24' PASS AT 30.05' 1033.95 N. 89°42 00 "W. 298.66 FEDERAL ROAD (50')

FEDERAL ROAD SCALE: 1" = 2000' VICINITY MAP

DEED REFERENCE:

JOHN MARK GOSSARD 96.87AC. - IST TRACT D.B. 288, PG. 932

LEGEND


O = 5/8" IRON ROD (Set) WITH PLASTIC CAP STAMPED "RLL 6106". ⊙ = P.K.NAIL (Set).

REFERENCE BEARING: N.89°42'00"W. - CENTERLINE OF FEDERAL ROAD AS PER D.B. 288, PG. 932 .

NOTES

THE ABOVE LISTED DEED REFERENCES WERE USED AS A BASIS FOR CARRYING OUT THE WORK. NO EVIDENCE OF OCCUPATION EXISTS ALONG PROPERTY LINES INDICATED BY SOLID LINES. ALL MONUMENTS FOUND OR SET ARE IN GOOD CONDITION UNLESS OTHERWISE INDICATED.

I HEREBY CERTIFY THIS TO BE A PLAT OF A SURVEY MADE UNDER MY DIRECTION IN | - 10 - 92



SURVEY OF 1.2914 AC. V.M.S. 10097 STOKES TOWNSHIP MADISON COUNTY, OHIO



McCARTY ASSOCIATES Engineers - Surveyors - Architects

213 N. High Street Hillsboro, Ohio 45133 (513) 393-9971

222 N. Oakland Avenue Washington C.H., Ohio 43160 (614) 335-3816

17-92

SCALE |" = 401 JAN., 1992

RONALD L. LINTON, P. S. 6106

20' 40' 120

DATE