IMPROVED	Wile - Warner MADISON CO. F No142	OAD RECORD	K BOOK MFG. CO., COL., O. 5908
	• • • • • • • • • • • • • • • • • • •	and the second s	Point
Class of Traffic	*	Dista	ance
Built by	Date	Pri	ce \$
Surveyed by		• •	
Thickness of foundation  Make of brick  Width  Crown  Cushion  Filler  Kind of curb  Size of curb  X-  [] yds brick	Mixture  Material {Gravel	Binder Size Wic	GRAVEL, ckness Ith wn yds, Mat
Total length O.20 Distance C. to C. Ditch No. of stone culverts No. of C. I. P. Orok Depth of Ditches	No. of steel br	to berm	of R. W. <u>40'</u> on, bridges wood bridges excavation on R. W.

## INSPECTION OF IMPROVED ROADS.

		_			•
Date of Inspection		* ,		• •	•
BRICK	_	ļ			
Condition of brick			ļ <u>.</u>	<u>_</u>	
Condition of filler			•		-
Condition of curb			ļ		•.
CONCRETE				. %	· .
Condition of concrete			,		<u> </u>
- Condition of surface	·				
SLAG-LIMESTONE					
Condition of foundation					<u> </u>
Condition of top			·		·
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
_ Condition of surface	_]				
Is road ruted		,	4		
GENERAL					
Condition of ditches			<u> </u>		<u> </u>
Condition of berms					l .
•				•	l
Laid out and Improved 1897 See Ad. Imp. Acc	13 page 103		,		