

Marvin Eugene Creamer
79.39 AC.
D.B.276, Pg.301


Government Radar
Station
Robert Williams-Owner



REFERENCE BEARING: N. 63°10'00"E. - C of OLD XENIA ROAD
AS PER D.B. 273 , PG. 161 .

DEED REFERENCE:
STEVEN L. & NANCY K. CREAMER
50 AC.
D.B. 273 , PG. 161

- LEGEND**
- = 5/8" IRON ROD (Set) WITH PLASTIC CAP STAMPED "RLL 6106"
 - ⊙ = P.K. Nail (Set)
 - ⊘ = P.K. Nail (Found)
 - = SPIKE (Found)



NOTES

THE ABOVE LISTED DEED REFERENCES WERE USED AS A BASIS FOR CARRYING OUT THE WORK.

NO EVIDENCE OF OCCUPATION EXISTS ALONG PROPERTY LINES INDICATED BY SOLID LINES.

ALL MONUMENTS FOUND OR SET ARE IN GOOD CONDITION UNLESS OTHERWISE INDICATED.

I HEREBY CERTIFY THIS TO BE A PLAT OF A SURVEY MADE UNDER MY DIRECTION IN NOV. , 1991

Ronald L. Linton
RONALD L. LINTON, P. S. 6106



SURVEY OF 2.1306 AC.		
V.M.S. 4387		
PAINT TOWNSHIP		
MADISON COUNTY, OHIO		
McCARTY ASSOCIATES Engineers - Surveyors - Architects		
213 N. High Street Hillsboro, Ohio 45133 (513) 393-9971	222 N. Oakland Avenue Washington C.H., Ohio 43160 (614) 335-3816	
DATE	SCALE	
NOV., 1991	1" = 50'	99-91