

Icertify all dimensions on the above Plat are correct, Iron Pin were set as shown and one encroachment found.

Survey of Lot No.9 of Elmhurst Village, London, Ohio, made for Wallace V. Nichols. 1960

Scale 1 = 20'

Registered Engineer No. 5851 9-26-60